

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for W10128087 Date: 10/31/2019	Laundry

Brands Affected    	Dryer door switch W10128087 Part(s) Affected: Dryer door switch part number W10128087 Concern: Dryer door switch part number W10128087 is no longer available and was subbing to W10318609. We are breaking the sub and making W10128087 CC91. Production did a digit change to a new switch W10350906 which has a different footprint and required a new front panel. Resolution: In order to solve this backorder issue service engineering has created kits that correspond to the models that used the old switch and old front panel. These kits will contain the new switch W10350906, the new version front panel, and technician instructions W10874318 or simply a kit W11041190 that contains a compatible switch 8283288 and door switch seal W10118614 when possible. When the door switch W10128087 is ordered, the call taker will direct the customer to the correct kit number by locating the switch kit that corresponds to the customers model number listed below. NOTE: If the customer's model is not found on this letter then unfortunately we do not currently have a solution. We added some color models to the letter; if the customer will accept a white front panel they can use the corresponding kits. I'll add the color models in <i>italics</i> so that they stand out.
--	--

ALL SPECIAL HANDLING
DOCUMENTS ONLINE:
<https://www.servicematters.com/>

Special Handling for Service Part(s)

For Immediate Attention of Your Parts Department

From: Consumer Services
Subject: Special Handling for W10128087
Date: 10/31/2019

Laundry

Dryer Door panel and switch kit W10874283 for the following models:

CED8990XW0	CEW9100VQ0	CEW9100WQ0	CGD8990XW0
CGD8990XW1	CGW9100VQ0	CGW9100WQ0	YCED8990XW0
YCED8990XW1	YCEW9100VQ0	YCEW9100WQ0	CET8000AQ0
CET8000AQ1	CET8000XQ0	CGT8000AQ0	CGT8000AQ1
CGT8000XQ0			

Kit contains the following parts:

- Front panel assembly W10551278 (White)
- Door switch W10350906
- Instruction Sheet W10874318

Dryer Door panel and switch kit W10874298 for the following models:

WED9150WW0	WED9250WR0	WED9250WW0	WED9270XR0
WED9270XW0	WGD9150WW0	WGD9250WR0	WGD9250WW0
YWED8300SB2	YWED8300SE2	YWED8300SW2	YWED9150WW0
YWED9250WR0	YWED9250WW0	YWED9270XR0	YWED9270XW0

Kit contains the following parts:

- Front panel assembly W10551275 (White)
- Door switch W10350906
- Instruction Sheet W10874318

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for W10128087 Date: 10/31/2019	Laundry

	Dryer Door panel and switch kit W10874299 for the following models:			
	WED9250WL0	WED9270XL0	WGD9250WL0	YWED9250WL0
	YWED9270XL0			
	Kit contains the following parts: • Front panel assembly W10551276 (Silver) • Door switch W10350906 • Instruction Sheet W10874318			
	Dryer Door panel and switch kit W10874300 for the following models:			
	IGD7300WW0	WED9050XW0	WGD9050XW0	YWED9050X0
	Kit contains the following parts: • Front panel assembly W10551277 (White) • Door switch W10350906 • Instruction Sheet W10874318			
	Door switch and door switch seal kit W11041190 for the following models:			
	110.86742700	110.86742701	110.86742702	110.86747700
	110.86747702	110.86757701	110.86762700	110.86762701
	110.87079602	110.87081601	110.87081602	110.87086601
	110.87086602	110.87087601	110.87087602	110.87088601
	110.87088602	110.87089601	110.87091601	110.87728701
	110.C86742700	110.C86742701	110.C86742702	110.C86747701
	110.C86747702	110.C86762700	110.C86762701	110.C86762702

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for W10128087 Date: 10/31/2019	Laundry

	110.C86762702	110.C87081602	110.C87086601	110.C87086602
	110.C87087601	110.C87087602	110.C87088601	110.C87088602
	110.C87089601	110.C87089602	110.C87091601	110.C87091602
	110.C87091603	110.C87091800	110.C87721700	110.C87721701
	110.C87721702	110.C87727701	110.C87727702	110.C87728702
	110.C87729700	110.C87729701	110.C87729702	110.C87731701
	110.C87731800	110.C87731801	110.C87737701	110.C87737702
	110.C87738701	110.C87738702	110.C87739701	110.C87739702
	110.C87751800	110.C87761800	110.C87872601	110.C87872603
	110.C87892601	110.C87892602	110.C87892603	110.C97081602
	110.C97091801	110.C97872602	110.C97872603	7MWGD9200TQ1
	7MWGD9400TU1	7MWGD9400TU2	YMEDE500VF1	YMEDE500VP1
	YMEDE500VW1	WED9200SQ1	WED9200SQ2	WED9300VU0
	WED9300VU1	WED9400SB1	WED9400ST1	WED9400SU1
	WED9400SU2	WED9400SW1	WED9400SW2	WED9400SZ1
	WED9400SZ2	WED9400VE0	WED9400VE1	WED9450WL0
	WED9450WL1	WED9450WR0	WED9450WR1	WED9450WW0
	WED9450WW1	WED9470WL1	WED9470WR1	WED9470WW1

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for W10128087 Date: 10/31/2019	Laundry

	WED9470WW2	WED9500TC0	WED9500TC1	WED9500TC2
	WED9500TU1	WED9500TW0	WED9500TW1	WED9500TW2
	WED9500TW3	WED9550WL0	WED9550WL1	WED9550WL2
	WED9550WR0	WED9550WR1	WED9550WR1	WED9550WW0
	WED9550WW1	WED9550WW2	WED9600TA0	WED9600TA1
	WED9600TA2	WED9600TB0	WED9600TB1	WED9600TU0
	WED9600TU1	WED9600TW0	WED9600TW1	WED9600TW2
	WED9600TZ0	WED9610XW0	WED9610XW1	WED9750WL0
	WED9750WL1	WED9750WR0	WED9750WW0	WED9750WW1
	WGD9200SQ0	WGD9200SQ1	WGD9300VU0	WGD9300VU1
	WGD9400SB1	WGD9400ST1	WGD9400SU1	WGD9400SW1
	WGD9400SW2	WGD9400SW3	WGD9400SZ1	WGD9400SZ2
	WGD9400SZ3	WGD9400VE0	WGD9400VE1	WGD9450WL0
	WGD9450WL1	WGD9450WL2	WGD9450WR0	WGD9450WR1
	WGD9450WR2	WGD9450WW0	WGD9450WW1	WGD9450WW2
	WGD9470WL1	WGD9470WL2	WGD9470WR1	WGD9470WR2
	WGD9470WW1	WGD9470WW2	WGD9470WW3	WGD9500TC0
	WGD9500TC1	WGD9500TC2	WGD9500TU1	WGD9500TW0

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for W10128087 Date: 10/31/2019	Laundry

	WGD9500TW1	WGD9500TW2	WGD9500TW3	WGD9500TW4
	WGD9550WL0	WGD9550WL1	WGD9550WL2	WGD9550WL3
	WGD9550WR0	WGD9550WR1	WGD9550WR2	WGD9550WW0
	WGD9550WW1	WGD9550WW2	WGD9550WW3	WGD9600TA0
	WGD9600TA1	WGD9600TA2	WGD9600TB0	WGD9600TB1
	WGD9600TU0	WGD9600TU1	WGD9600TW0	WGD9600TW1
	WGD9600TW2	WGD9600TZ0	WGD9610XW0	WGD9610XW1
	WGD9750WL0	WGD9750WL1	WGD9750WL2	WGD9750WR0
	WGD9750WR1	WGD9750WW0	WGD9750WW1	WGD9750WW2
	YWED9200SQ1	YWED9200SQ2	YWED9300VU0	YWED9300VU1
	YWED9400SU1	YWED9400SU2	YWED9400SW1	YWED9400SW2
	YWED9400SZ1	YWED9400VE0	YWED9400VE1	YWED9450WL0
	YWED9450WL1	YWED9450WR0	YWED9450WR1	YWED9450WW0
	YWED9450WW1	YWED9470WL1	YWED9470WR1	YWED9470WW1
	YWED9500TC1	YWED9500TU0	YWED9500TU1	YWED9550WL0
	YWED9550WL1	YWED9550WL2	YWED9550WR0	YWED9550WR1
	YWED9550WW0	YWED9550WW1	YWED9550WW2	YWED9600TA0
	YWED9600TA1	YWED9600TA2	YWED9600TB0	YWED9600TB1

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	<i>From: Consumer Services</i> <i>Subject: Special Handling for W10128087</i> <i>Date: 10/31/2019</i>	<i>Laundry</i>

	YWED9600TU0	YWED9600TW0	YWED9600TU1	YWED9600TW1
	YWED9600TW2	YWED9600TZ0	YWED9750WL0	YWED9750WR0
	YWED9750WW0			
	Kit contains the following parts: • Door switch 8283288 • Door switch seal W10118614			