

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for 8574875 Date: 11/09/2009	Laundry

Brands Affected  	Dryer Door Switch 8574875																	
	Part(s) Affected: Dryer Door Switch part number 8574875 Concern: Dryer door switch part number 8574875 is no longer available and was subbing to W10318609. After further investigation we are breaking that sub and making 8574875 CC91. Production did a digit change to the new switch W10350906 which has a different footprint and required a new front panel. Resolution: In order to solve this backorder issue service engineering has created kits that correspond to the models that used the old switch and old front panel. These kits will contain the new switch W10350906, the new version front panel, and technician instructions W10874318 or simply a kit W11041190 that contains a compatible switch 8283288 and door switch seal W10118614 when possible. When the door switch 8574875 is ordered, the call taker will direct the customer to the correct kit number by locating the switch kit that corresponds to the customers model number listed below. NOTE: If the customer's model is not found on this letter then unfortunately we do not currently have a solution. We added some color models to the letter; if the customer will accept a white front panel they can use the corresponding kits. I'll add the color models in <i>italics</i> so that they stand out. Dryer Door panel and switch kit W10874283 for the following models: <table border="1"> <tbody> <tr> <td>MDE22PDAYW0</td><td>MDE22PDAZW0</td><td>MDE22PRAYW0</td><td>MDE22PRAZW0</td></tr> <tr> <td>MDG22PDAWW0</td><td>MDG22PDAWW0</td><td>MDG22PRAWW0</td><td>7MMGD0100TQ0</td></tr> <tr> <td>7MMGD0100TQ1</td><td>7MMGD0600TBO</td><td>7MMGD0600TB1</td><td>MEDZ400TQ1</td></tr> <tr> <td>MEDZ400TQ2</td><td>MEDZ600TB1</td><td>MEDZ600TB2</td><td>MEDZ600TE2</td></tr> </tbody> </table>			MDE22PDAYW0	MDE22PDAZW0	MDE22PRAYW0	MDE22PRAZW0	MDG22PDAWW0	MDG22PDAWW0	MDG22PRAWW0	7MMGD0100TQ0	7MMGD0100TQ1	7MMGD0600TBO	7MMGD0600TB1	MEDZ400TQ1	MEDZ400TQ2	MEDZ600TB1	MEDZ600TB2
MDE22PDAYW0	MDE22PDAZW0	MDE22PRAYW0	MDE22PRAZW0															
MDG22PDAWW0	MDG22PDAWW0	MDG22PRAWW0	7MMGD0100TQ0															
7MMGD0100TQ1	7MMGD0600TBO	7MMGD0600TB1	MEDZ400TQ1															
MEDZ400TQ2	MEDZ600TB1	MEDZ600TB2	MEDZ600TE2															

ALL SPECIAL HANDLING DOCUMENTS ONLINE:
<https://www.servicematters.com/>

Special Handling for Service Part(s)

For Immediate Attention of Your Parts Department

From: Consumer Services
Subject: Special Handling for 8574875
Date: 11/09/2009

Laundry

MEDZ600TK1	MEDZ600TK2	MEDZ600TW1	MEDZ600TW2
MGDZ400TQ1	MGDZ400TQ2	MGDZ600TB1	MGDZ600TK1
MGDZ600TW1	YMEDZ400TQ0	YMEDZ400TQ2	YMEDZ600TB0
YMEDZ600TB2	YMEDZ600TE2	YMEDZ600TK2	YMEDZ600TW0
YMEDZ600TW2			

Kit contains the following parts:

- Front panel assembly W10551278 (White)
- Door switch W10350906
- Instruction Sheet W10874318

Dryer door switch and door switch seal kit W11041190 for the following models:

7MGGW9200MW3	7MMGE9959TB0	7MMGE9959TW0	7MWGD9200TQ0
7MWGD9400TU0	110.85081401	110.85087401	110.85088401
110.85089401	110.85091401	110.85861401	110.85862401
110.85866401	110.85872401	110.85874401	110.85876401
110.97721700	110.97729700	110.C85081401	110.C85087401
110.C85088401	110.C85089401	110.C85861401	110.C85862401
110.C95081402	110.C95862402	110.C97081601	110.C97721700
110.C97872601	KGHS02RMT2	KGHS02RWH2	MED9600SQ0
MED9800TK0	MGD9600SQ0	MGD9800TB0	YMED9600SQ0
YMED9600TK0	YMED9800TB0	YMED9800TK0	GEW9250SU0
GGW9250PL3	GGW9250PT3	GGW9250PW3	GGW9250SU0
GGW9260PL3	GGW9260PW3	WED9200SQ0	WED9400SB0

Special Handling for Service Part(s)

For Immediate Attention of Your Parts Department

From: Consumer Services
Subject: Special Handling for 8574875
Date: 11/09/2009

Laundry

WED9400ST0	WED9400SU0	WED9400SW0	WED9400SZ0
WED9500TU0	WED9600SU0	WGD9400SB0	WGD9400ST0
WGD9400SU0	WGD9400SW0	WGD9400SZ0	WGD9500TU0
WGD9600SU0	YGEW9250SU0	YMED9600SQ0	YMED9800TB0
YMED9800TK0	YWED9200SQ0	YWED9400SU0	YWED9400SW0
YWED9400SZ0			

Kit contains the following parts:

- Door switch 8283288
- Door switch seal W10118614

Dryer Door panel and switch kit W10874298 for the following models:

7MWGD8300SW0	7MWGD8300SW1	7MWGD8500SR0	7MWGD8500SR1
7MWGD8500SR2	WED8300SB0	WED8300SB1	WED8300SB2
WED8300SE2	WED8300SW0	WED8300SW1	WED8300SW2
WED8410SW0	WED8410SW1	WED8410SW2	WED8500SR0
WGD8300SB0	WGD8300SB1	WBD8300SB2	WGD8300SE3
WGD8300SW0	WGD8300SW1	WGD8300SW2	WGD8410SW0
WGD8410SW1	WGD8500SR0	WGD8500SR1	YWED8300SB0
YWED8300SB1	YWED8300SW0	YWED8300SW1	YWED8410SW2
YWED8500SR0	YWED8500SR1	YWED8500SR2	

Kit contains the following parts:

- Front panel assembly W10551275 (White)
- Door switch W10350906
- Instruction Sheet W10874318

Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	From: Consumer Services Subject: Special Handling for 8574875 Date: 11/09/2009	Laundry

	Dryer Door panel and switch kit W10874300 for the following models:			
	110.86562501	110.86572501	110.87511700	110.87511701
	110.87531700	110.87531701	110.87531702	110.87561601
	110.87561602	110.87561603	110.87562601	110.87562602
	110.87562603	110.87571601	110.87571602	110.87571603
	110.87572601	110.87572602	110.87572603	110.87581601
	110.87582601	110.87566601	110.87566602	110.87566603
	110.87567700	110.87567701	110.87576601	110.87576602
	110.87576603	110.97562601	110.97566601	110.C87561600
	110.C87561601	110.C87561602	110.C87562600	110.C87562601
	110.C87562602	110.C87566600	110.C87566601	110.C87566602
	110.C87567700	110.C87567701	110.C87571600	110.C87571601
	110.C87572601	110.C87576601	110.C87581600	110.C87582600
	110.C87582601	110.C87582602	110.C96562501	110.C97561601
	110.C97561602	110.C97562600	110.C97562601	110.C97562602
	110.C97572600	110.C97582600	110.C97566601	110.C97566602
	110.C975567700			
	Kit contains the following parts: • Front panel assembly W10551277 (White) • Door switch W10350906 • Instruction Sheet W10874318			