


Special Handling for Service Part(s)	For Immediate Attention of Your Parts Department	
	<i>From: Consumer Services</i> <i>Subject: Special Handling for W10048200</i> <i>Date: 06/26/2010</i>	Laundry

<p style="color: red; font-weight: bold;">Brands Affected</p> 	<h2 style="margin: 0;">Center User Interface (W10048200)</h2> <p>Part(s) Affected:</p> <p>ADOTT dryer units</p> <p>Concern:</p> <p>Part W10048200 is a Center User Interface used on the ADOTT dryer units which use both Center and Right (Modifier) User Interface Boards. The LED Driver has been replaced and as a result the Center and Right (Modifier) User Interface boards must be matched so that the customer does not get one board that is the old version and one board that is the new version.</p> <p>Resolution:</p> <p>Kit numbers have been assigned, for the various modifiers used with the common center tech frame. When a customer calls for part W10048200, the modifier needs to be identified to determine the kit needed by using the RPL (Repair Parts Lists). The BOM's (Bill of Materials) could have been updated with the newer Center & Modifier part numbers.</p> <p>W10339925 – Contains the W10048200 Center and W10023360 Right (Modifier) boards.</p> <p>W10339926 – Contains the W10048200 Center and W10048221 Right (Modifier) boards.</p> <p>W10339928 – Contains the W10048200 Center and W10172233 Right (Modifier) boards.</p> <p>W10339956 – Contains the W10280556 Center and W10280641 Right (Modifier) boards.</p> <p>NOTE: Kit W10339956 replaces the center W10048200 & Modifier W10172236.</p>
---	---

ALL SPECIAL HANDLING DOCUMENTS ONLINE:
<https://www.servicematters.com/>