Special Handling for Service Part(s)

For Immediate Attention of Your Parts Department

From: Consumer Services

Subject: Special Handling for W10156252

Date: 5/9/2011

Laundry

Brands Affected

Whirlpool®



Switch W10156252

Part(s) Affected: W10156252

Concern: A running change was made in production going from one common switch to two different switches that are not interchangeable.

Resolution: When a customer places an order for W10156252, they will need to supply a model number of the unit to assure they get the proper switch. Refer to the model number list below for the correct switch:

Models Using W10415587		Models Using W10249845		
WFW9700VW00	WFW9500TW00	WFW9700VW01	WFW9500TW02	
WFW9700VA00	WFW9500TC00	WFW9700VA01	WFW9500TC02	
MHWE500VW00	WFW9500TW01	MHWE500VW01	WFW9600TW02	
MHW500VP00	WFW9500TC01	MHWE500VP01	WFW9600TA02	
MHWE900VW00	WFW9600TW00	MHWE900VW01	MHWE500VW12	
MHWE900VJ00	WFW9600TA00	MHWE900VJ01	110.47781702	
110.47787800	WFW9600TW01	110.47787801	110.47791702	
110.47788800	WFW9600TA01	110.47788801	110.47789702	
110.47797800	MHWE500VW10	110.47797801	110.47799702	
110.47798800	MHWE500VW11	110.47798801	110.46742702	
110.47751800	110.47781700	110.47751801	110.46752702	
110.47761800	110.47791700	110.47761801	110.46747802	
	.			
Models Using W10415587		Models Using W10249845		

ALL SPECIAL HANDLING DOCUMENTS ONLINE: https://www.servicematters.com/

☐ Page 1

Special Handling for Service Part(s)

For Immediate Attention of Your Parts Department

From: Consumer Services

Subject: Special Handling for W10156252

Date: 5/9/2011

Laundry

110.47701800	110.47789700	110.47701801	110.46757802
110.46742700	110.47781701	WFW9550WW00	WFW9550WR00
110.46752700	110.47791701	WFW9550WL00	
110.46742701	110.47789701		
110.46752701	110.47799701		
110.46747801	110.46757801		